



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Th re Patent Application of:

Hideki IWATA et al.

Application No.: 10/634,876

ATTENTION

Confirmation No.: 8217

CERTIFICATE OF CORRECTION

Filed: August 6, 2003

BRANCH

U.S. Patent No.: 7,551,048

Certificate

Issued: June 23, 2009

SEP 2:1 2009

For: MICRO-RELAY AND METHOD OF FABRICATING THE SAME

of Correction

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

Patentees respectfully request that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY L

Data

7/17/09

By: _

William F. Herbert Registration No. 31,024

1201 New York Ave, N.W., 7th Floor

Washington, D.C. 20005 Telephone: (202) 434-1500 Facsimile: (202) 434-1501 PTO/SB/ 44 (08-00)
Approved for use through 09/30/2000. OMB 0651-0033
U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE

	CERTIFICATE OF CORRECTION
	PATENT NO : 7,551,048
	DATED : June 23, 2009
	INVENTOR(S) : Hideki IWATA et al.
	Column 63, Line 54, change "transmissions," totransmission,
•	
•	

MAILING ADDRESS OF SENDER: **STAAS & HALSEY LLP** 1201 New York Ave., N.W. 7th Floor Washington, DC 20005

PATENT NO. 7,551,048

No. of add'l copies @ 50¢ per page